

Bluegrass Diesel Specialist's, Inc.

1663 Production Drive
Burlington, KY 41005

Phone: 859-282-8785
Fax: 859-372-2473

Page 1 of 2

Invoice Number: 33261
Invoice Date: 06/22/2007
Invoice Time: 03:24 PM
Repair Order: 3286
Customer: BE
Warehouse: Bluegrass

Bill To: Brass Eagle Excavation
7601 Hwy 42
Florence, KY 41042

Ship To: Brass Eagle Excavation
7601 Hwy 42
Florence, KY 41042

Phone: 283-9028

Fax:

Customer P/O:

Unit Number: R-43
Meter Reading: 648,635 Miles

Year: 1995
Manufacturer: Volvo
Model:
VIN: 4V1JBBJ2GSR838066

Unit Components:

<u>Manufacturer</u>	<u>Model</u>	<u>Description</u>	<u>Serial Number</u>
Cummins	N-14	Engine	11771351

Job: 1 **Dept: Shop** **ECS** **Engine Cooling Repair**

Complaint: Coolant leak at the radiator core.

Cause: Rotted core.

Correction: Pull radiator and send out to be recored. Reassemble replacing all frayed belts, necc hoses and clamps. Refill system with new coolant and conditioner. Test drive and heard a exhaust noise. Ck and found a def clamp, install new. Recheck, all ok.

Part/Labor	Description/Reference	Unit of Measure	Quantity	Price	Extended Price
3066285	Thermostat Gasket	EA	1.00	\$1.62	\$1.62
3076492	Serp Belt	EA	1.00	\$16.97	\$16.97
90893K	Tube Connector	EA	1.00	\$56.17	\$56.17
07480	Roloc Disc	EA	2.00	\$1.41	\$2.82
28662	3/8 Hose	EA	6.00	\$4.04	\$24.24
215SB165BP3	T-Stat Kit	EA	1.00	\$51.89	\$51.89
25-9440	Belt	EA	1.00	\$17.86	\$17.86
4752-029R	1/4-20 Nut	EA	1.00	\$0.14	\$0.14
4752-030R	5/16-18 Nut	EA	1.00	\$0.19	\$0.19
705-1507	Hi-Torque Clamp	EA	4.00	\$7.27	\$29.08
705-1527	Hi-Torque Clamp	EA	2.00	\$8.76	\$17.52
8073-029R	1/4 Flat Washer	EA	2.00	\$0.12	\$0.24
25-080435	Serp Belt	EA	1.00	\$31.56	\$31.56
25-9385	V-Belt	EA	1.00	\$17.11	\$17.11
4056	Coolant Conditioner	EA	4.00	\$4.87	\$19.48
501-542R	1/4-20x1 Bolt	EA	1.00	\$0.24	\$0.24
705-1173	Hose Clamp	EA	4.00	\$1.89	\$7.56
89-G-21-5050-61	Serv Pro Anti-Freeze, Gal 50/50 Comple	EA	8.00	\$9.44	\$75.52
21917-0002	Insulator	EA	2.00	\$22.18	\$44.36
21917-0003	Insulator	EA	2.00	\$22.18	\$44.36
SB	Sublet- Radiator Recore/0036997	EA	1.00	\$1,005.75	\$1,005.75

Bluegrass Diesel Specialist's, Inc.

1663 Production Drive
Burlington, KY 41005

Phone: 859-282-8785
Fax: 859-372-2473

Page 2 of 2

Invoice Number: 33261
Invoice Date: 06/22/2007
Invoice Time: 03:24 PM
R/O: 3286
Customer: BE
Warehouse: Bluegrass

Job 1 Subtotals	
Parts:	\$458.93
Core Charges:	\$0.00
Core Returns:	\$0.00
Labor:	\$578.50
Miscellaneous:	\$1,005.75
Shop Supplies:	\$46.28
EPA Charge:	\$0.00
Job 1 Subtotals	\$2,089.46

Detail Tax Information
\$30.31 Ky Sales Tax

Total Parts:	\$458.93
Total Core Charges:	\$0.00
Total Core Returns:	\$0.00
Total Labor:	\$578.50
Total Miscellaneous:	\$1,005.75
Total Shop Supplies:	\$46.28
Total Environmental Charge:	\$0.00
Invoice Subtotal:	\$2,089.46
Total Tax:	\$30.31

Invoice Due Date: 06/22/2007

Sale Type: Cash Sale

Warranty varies with product. Contact your sales representative about your particular product.

Invoice Total: \$2,119.77



Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0001737
Date Printed : 10/1/09
Page : 1
Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028

Ext :

Phone 2 : (859) 512-5022

Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 664306

Parts

Quan	Part Number	Description	Price
1.00	10461053RMAN	STARTER	303.75

Labor

Op	Tech	Description	Time	Charge
AL	003 WH	COMPLAINT: INSPECT ALL STARTER CALBES. CAUSE:NEGITIVE CABLE POST DAMAGED CORRECTION:ISOLATE AND ATTEMP TO REPAIR AS NEEDED. UNABLE TO REPAIR STARTER. REMOVE ALL INTERFERRING PARTS R&R SARTER AS REQUIRED TEST AFTER OK.		246.00

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in truck in case of fire, theft or any other cause beyond our control.

x

Labor :	\$246.00
Parts :	\$303.75
Sublet :	\$0.00
Other Fees :	\$0.00
Supplies :	\$21.99
Subtotal :	\$571.74
Sales Tax :	\$19.54

Paid By :	Total :	\$591.28
On Account	Paid :	\$0.00
Pay Ref :	Due :	\$591.28

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0002214

Date Printed : 8/27/10

Page : 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028

Ext : MAIN

Phone 2 : (859) 512-5022

Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 667358

Parts

Quan	Part Number	Description	Price
1.00	3090942RX	PUMP FUEL N/14	1012.50
1.00	4026171	GASKET F/P	10.79
1.00	3046200	SPIDER F/P	8.09
1.00	3166389	TUBE FUEL	31.05
1.00	FF1057	FILTER	28.69

Labor

Op	Tech	Description	Time	Charge
LP	005 WH	COMPLAINT: CHECK LOW BOOST PRESSURE.		410.00
		CAUSE:FUEL PUMP BAD		
		CORRECTION:TROUBLE-SHOOTED AND TEST		
		DROVE HAD 150PSI AT IDLE RUNNING DOWN		
		ROAD 160 TO 180PSI ALL OK PUMP WONT REV		
		OUT AT TIMES. REMOVED ALL INTERFERING		
		PARTS AND REMOVED AND REPLACED FUEL PUMP		
		AND HOOKED ALL LINES UP AND RETEST		
		DROVE ALL OK.		

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in truck in case of fire, theft or any other cause beyond our control.

x _____

Labor :	\$410.00
Parts :	\$1,091.12
Sublet :	\$0.00
Other Fees :	\$0.00
Supplies :	\$32.54
Subtotal :	\$1,533.66
Sales Tax :	\$67.42

Paid By :	Total :	\$1,601.08
On Account	Paid :	\$0.00
Pay Ref :	Due :	\$1,601.08

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0002203

Date Printed : 8/16/10

Page : 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028 Ext : MAIN

Phone 2 : (859) 512-5022 Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 667208

Parts

Labor

Quan	Part Number	Description	Price
4.00	FFORCE	ANTIFREEZE	49.40
2.00	R134A	FREON	32.00
1.00	4058981	GASKET	38.46
4.00	3050667	SEAL	4.88
1.00	69079	DYE A/C	8.10

Op	Tech	Description	Time	Charge
AC 001		SUB COMPLAINT: A/C SYSTEM NOT WORKING.		164.00
		CAUSE:NO FREON		
		CORRECTION:RECOVERED SYSTEM HAD NO		
		FREON IN SYSTEM, VACUAMED, LEAK TEST ALL		
		OK, CHARGED SYSTEM RAN AND CHECKED FOR		
		LEAKS ALL OK. INSTALL DYE IN AC SYSTEM		
CO 001	WH	COMPLAINT: CHECK COOLANT LEAK		574.00
		CAUSE:ADAPTER LEAKING		
		CORRECTION:REMOVED INTERFERING PARTS AND		
		REMOVED CENTER ROCKER BOX, REMOVED BOTH		
		COOLANT ADAPTERS AND RESEALED AND PUT		
		ALL BACK TOGETHER AND ADJUSTED ALL		
		VALVES AND INJECTORS ALL OK.		

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
----	-----	----------------	----	-----	----------------	----	-----	----------------

OK

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in truck in case of fire, theft or any other cause beyond our control.

X _____

Labor :	\$738.00
Parts :	\$132.84
Sublet :	\$0.00
Other Fees :	\$0.00
Supplies :	\$32.54
Subtotal :	\$903.38
Sales Tax :	\$9.92

Paid By :	Total :	\$913.30
On Account	Paid :	\$0.00
Pay Ref :	Due :	\$913.30

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0002301

Date Printed : 10/7/10

Page : 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028 Ext : MAIN

Phone 2 : (859) 512-5022 Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 667697

Parts

Labor

Quan Part Number Description Price

Op Tech Description Time Charge
LP 005 BP COMPLAINT: CHECK LOW BOOST PRESSURE. 82.00

CAUSE:PARAMETERES

CORRECTION:MAKE NESSECARY CHANGES IN THE
ECM AS REQUIRED

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in truck in case of fire, theft or any other cause beyond our control.

x _____

Labor : \$82.00

Parts : \$0.00

Sublet : \$0.00

Other Fees : \$0.00

Supplies : \$5.64

Subtotal : \$87.64

Sales Tax : \$0.34

Paid By : Total : \$87.98

On Account

Pay Ref : Paid : \$0.00

Due : \$87.98

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0002389

Date Printed : 11/26/10

Page : 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028

Ext : MAIN

Phone 2 : (859) 512-5022

Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 668837

Parts

Labor

Quan Part Number Description Price

Op Tech Description Time Charge
 SC 001 BP (11/18/2010) SERVICE CALL 180.00

COMPLAINT: TRUCK WILL NOT START
 CAUSE: UNKNOWN
 CORRECTION: NO PROBLEM FOUND. DROVE TRUCK
 BACK TO MAINLAND DIESEL FOR REPAIRS.
 STILL NO PROBLEM FOUND. SCAN AND CHECKED
 FOR CODES. OK

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in truck in case of fire, theft or any other cause beyond our control.

X

Labor : \$180.00

Parts : \$0.00

Sublet : \$0.00

Other Fees : \$0.00

Supplies : \$7.20

Subtotal : \$187.20

Sales Tax : \$0.43

Paid By : Total : \$187.63

On Account Paid : \$0.00

Pay Ref : Due : \$187.63

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0003047

Date Printed : 4/30/12

Page : 1

Center : 1

Customer : BRASS EAGLE EXCAVATION Address : 7601 HWY 42 FLORENCE City : FLORENCE, KY 41042- Phone 1 : (859) 283-9028 Ext : MAIN Phone 2 : (859) 512-5022 Ext : CELL	Vehicle : 1995 VOL CONV Unit : R-43 HP : 310 VIN : SR838066 Engine : 11771351 Trans : 8 Mileage : 673064
--	---

Parts				Labor			
Quan	Part Number	Description	Price	Op Tech	Description	Time	Charge
2.00	D6224-1114	BATT POS	51.84	EN 008 BP	COMPLAINT:NO START/HARD START		85.00
1.00	USED ECM	CELECT N14	977.50		CAUSE:BATTERIES		
1.00	3087560	INJECTOR REMAN	485.72		CORRECTION: BATTERIES WILL DIE AFTER		
4.00	HP31SH	BATTERY	396.00		JUST A FEW TIME IF CRANKING.		
					REPLACE BATTIRIES AS REQUIRED		
				FGT001	SUB INBOUND AND/OR OUTBOUND FREIGHT		59.00
					ECM SHIPPED AND CORE RETURNED		
				CD 007	SUB RERATE ECM TO 330 HP		350.00
					PROGRAM AS REQUIRED		
				CD 006 BP	COMPLAINT: HOOK UP SCAN TOOL AND CHECK		340.00
					FOR CODES.		
					CAUSE:NO START SOMETIMES		
					CORRECTION:ISOLATE PROBLEM AND FOUND ECM		
					NOT RESPONDING. INSTALL A USED ECM.		
					NOTE:		
					SEE RE PROGRAMMING		
				LP 004 WH	COMPLAINT: CHECK ENGINE MISFIRE.		255.00
					CAUSE:#5 INJECTOR SPRING BROKE		
					CORRECTION:REPLACE #5 INJECTOR.		
					PERFORM COMPLETE VALVE ADJUSTMENT		

OK Bad	Recommendation	OK Bad	Recommendation
OK			

I authorize the repair work, parts, materials and hereby grant MDC permission to operate the vehicle herein described at MDC's discretion for the purpose of testing. A mechanic's lien will be against the above vehicle to secure the amount of repairs thereto. There will be 2% monthly interest charges for over 30 days. Attorney & court fees will be charged if necessary. I understand MDC is not responsible for delay or other consequences due to the unavailability of parts shipments beyond MDC's control. MDC is NOT responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond their control.

X _____

Labor :	\$1,089.00
Parts :	\$1,911.06
Sublet :	\$0.00
Other Fees :	\$0.00
Supplies :	\$32.54
Subtotal :	\$3,032.60
Sales Tax :	\$116.62

Paid By :	Total :	\$3,149.22
On Account	Paid :	\$0.00
Pay Ref :	Due :	\$3,149.22

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0003833

Date Printed : 7/31/14

Page : 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028

Ext : MAIN

Phone 2 : (859) 512-5022

Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 681050

Parts

Quan	Part Number	Description	Price
1.00	3084473RX	ECM REMAN	2847.60
2.00	50/50	COOLANT	21.58

Labor

Op Tech	Description	Time	Charge
WR 001 SUB	SUBLET TOWING:10143...		395.00
	DATE:7/24/14		
	FROM:JOB SITE...		
	TO:MAINLAND DIESEL...		
CD 007 BP	CHECK ECM AS NEEDED FOR PERFORMANCE AND FUEL MILEAGE...		600.00
	PROGRAM TO 370HP AS REQUIRED...		
CL 001 BP	COMPLAINT:CHECK CLUTCH ADJUSTMENT...		68.00
	CAUSE:MAINTENANCE...		
	CORRECTION:ADJUST CLUTCH AS REQUIRED...		
CD 006 SUB	COMPLAINT:HOOK UP SCAN TOOL AND CHECK FOR CODES...		245.00
	CAUSE:SERVICE CALL TO CHECK NO START...		
	CORRECTION:ISOLATE AND TRUCK CRANKED AND STARTED UP...		
	TOW TRUCK AND CHECK ISOLATE ECM HAS FAILED...		
	REPLACE ECM AS REQUIRED...		
CO 001 BP	COMPLAINT:CHECK COOLANT LEAK...		8.50

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I authorize the repair work, parts, materials and hereby grant MDC permission to operate the vehicle herein described at MDC's discretion for the purpose of testing. A mechanic's lien will be against the above vehicle to secure the amount of repairs thereto. There will be 2% monthly interest charges for over 30 days. Attorney & court fees will be charged if necessary. I understand MDC is not responsible for delay or other consequences due to the unavailability of parts shipments beyond MDC's control. MDC is NOT responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond their control.

x

Labor :	\$1,316.50
Parts :	\$2,869.18
Sublet :	\$0.00
Other Fees :	\$0.00
Supplies :	\$32.54
Subtotal :	\$4,218.22
Sales Tax :	\$174.10

Paid By :	Total :	\$4,392.32
On Account	Paid :	\$0.00
Pay Ref :	Due :	\$4,392.32

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0003937

Date Printed : 12/31/14

Page : 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028

Ext : MAIN

Phone 2 : (859) 512-5022

Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 683582

Parts

Labor

Quan	Part Number	Description	Price	Op Tech	Description	Time	Charge
2.00	35058	SEAL STEER	91.80	AW 001 SUB COMPLAINT:CHECK LEAKING HUBS...			510.00
2.00	HM212011	BEARING CUP	32.38		CAUSE:SEAL LEAKING AND CAUSED THE		
2.00	HM212049	BEARING CONE	56.68		BEARINGS TO SEIZE...		
2.00	3782	BEARING CONE	40.48		CORRECTION:REPLACE THE LEFT AND RIGHT		
2.00	3720	BEARING CUP	20.84		SIDE STEER AXLE BRAKES, BEARINGS, RACES,		
2.00	4702QP23K	SHOE BRAKE	140.40		SEALS, NUTS, WASHERS, AND CAPS...		
2.00	1612	HUBCAP	51.78	WR 001 SUB SUBLET TOWING:			375.00
1.00	AXLE NUTS	AXLE WASHERS	33.08		DATE:12/8/14		
1.00	LUC-10088	LUCAS HUB OIL	12.15		FROM:160MM I 75 NORTH BOUND...		
1.00	3966106	TANK COOLANT	136.26		TO: MAINLAND DIESEL...		

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I authorize the repair work, parts, materials and hereby grant MDC permission to operate the vehicle herein described at MDC's discretion for the purpose of testing. A mechanic's lien will be against the above vehicle to secure the amount of repairs thereto. There will be 2% monthly interest charges for over 30 days. Attorney & court fees will be charged if necessary. I understand MDC is not responsible for delay or other consequences due to the unavailability of parts shipments beyond MDC's control. MDC is NOT responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond their control.

X

Labor : \$885.00
Parts : \$615.85
Sublet : \$0.00
Other Fees : \$0.00
Supplies : \$32.54
Subtotal : \$1,533.39
Sales Tax : \$38.90

Paid By : Total : \$1,572.29
On Account
Pay Ref : Paid : \$0.00
Due : \$1,572.29

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order # 0004078

Date : 10/1/2015

Page 1 of 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 3248 RAINBOW TER.

City : ERLANGER, KY 41018-2229

Phone 1 : (859) 283-9028

Ext : MAIN

Phone 2 : (859) 512-5022

Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Fleet #:

Engine : 11771351

Trans : 8

Mileage : 687206

Parts

Quan	Part Number	Description	Price
9.00	55422	HOSE	97.11
1.00	1/4 X 1	COURSE BOLT	0.66
1.00	1/4 NUT	COURSE NUT	0.27
2.00	1/4 FLAT WASHER	FLAT WASHER	0.78
1.00	1/4 FINE	FINE NUT	0.26
4.00	32605	OELL CLAMP	3.80
1.00	2199002	SWITCHQ	22.99
1.00	2399020	THERMOSTAT	35.99
1.00		IN FREIGHT	12.00
5.00	R134A	FREON	90.00
8.00	2491	PAG OIL 150	16.00
2.00	450012	FERRULE	16.18

Payments:

OnAcct, on 10/01/15

\$997.57

Labor

Op	Tech	Description	Time	Charge
AC	001	JLH COMPLAINT:A/C SYSTEM NOT WORKING...		650.00
		CAUSE:NO FREON...		
		CORRECTION:ISOLATE FREON LEAK TO THE		
		SUCTION LINE ON THE FRAME IS RUSTED...		
		INSTALL A CUSTOM FIT LINE AND SECURE...		
		VAC, INSTALL OIL, AND CHARGE SYSTEM...		
		INSTALL NEW FAN AND TEMP CONTROL		
		SWITCHES...		

OK Bad

Recommendation

OK Bad

Recommendation

OK Bad

Recommendation

OK

I authorize the repair work, parts, materials and hereby grant MDC permission to operate the vehicle herein described at MDC's discretion for the purpose of testing. A mechanic's lien will be against the above vehicle to secure the amount of repairs thereto. There will be 2% monthly interest charges for over 30 days. Attorney & court fees will be charged if necessary. I understand MDC is not responsible for delay or other consequences due to the unavailability of parts shipments beyond MDC's control. MDC is NOT responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond their control.

x

Labor : \$650.00

Parts : \$284.04

Sublet : \$0.00

Other Fees : \$12.00

Supplies : \$32.54

Subtotal : \$978.58

Sales Tax : \$18.99

Paid By :

Total : \$997.57

On Account

Pay Ref :

Paid : \$0.00

Due : \$997.57

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order #0003833

Date Printed : 7/31/14

Page : 2

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 7601 HWY 42 FLORENCE

City : FLORENCE, KY 41042-

Phone 1 : (859) 283-9028 Ext : MAIN

Phone 2 : (859) 512-5022 Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Engine : 11771351

Trans : 8

Mileage : 681050

Parts

Labor

Quan	Part Number	Description	Price	Op	Tech	Description	Time	Charge
						CAUSE:COOLANT LOW...		
						CORRECTION:TOP OFF COOLANT...		

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I authorize the repair work, parts, materials and hereby grant MDC permission to operate the vehicle herein described at MDC's discretion for the purpose of testing. A mechanic's lien will be against the above vehicle to secure the amount of repairs thereto. There will be 2% monthly interest charges for over 30 days. Attorney & court fees will be charged if necessary. I understand MDC is not responsible for delay or other consequences due to the unavailability of parts shipments beyond MDC's control. MDC is NOT responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond their control.

x _____

Labor : \$1,316.50
Parts : \$2,869.18
Sublet : \$0.00
Other Fees : \$0.00
Supplies : \$32.54
Subtotal : \$4,218.22
Sales Tax : \$174.10

Paid By : **Total :** \$4,392.32
On Account
Pay Ref : **Paid :** \$0.00
Due : \$4,392.32

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order # 0004245

Date : 6/30/2016

Page 1 of 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 3248 RAINBOW TER.

City : ERLANGER, KY 41018-2229

Phone 1 : (859) 283-9028 Ext : MAIN

Phone 2 : (859) 512-5022 Ext : CELL

Vehicle : 1995 VOL CONV

Unit : R-43

HP : 310

VIN : SR838066

Fleet #:

Engine : 11771351

Trans : 8

Mileage : 688000

Parts

Quan	Part Number	Description	Price
2.00	5-676X	U-JOINT 1810	269.98
1.00	GREASE	LUBE	9.99
1.00	MEG102D-20	SMALL DUMP PUMP	425.00
1.00	6.5-4-3821-1	YOKE TRANS	344.34
1.00		IN FREIGHT	35.00
2.00	50W OIL	TRANS LUBE	83.76
2.00		OIL DISPOSAL	1.80

Payments:

OnAcct, on 06/30/16 }1860.45

Labor

Op	Tech	Description	Time	Charge
TA	002 BP	COMPLAINT:PTO WONT ENGAGE/DISENGAGE... CAUSE:ISOLATE AND REPAIR FAILED PUMP... CORRECTION:TEST CHECK AND REPLACE THE HYDRAULIC PUMP AS REQUIRED MAKING ALL REQUIRED ADJUSTMENTS...		0.00
DL	001 BP	COMPLAINT:CHECK ALL U-JOINTS/YOKES... CAUSE:U JOINT CAPS ARE SPINNING IN THE YOKE, AND THE YOKE IS DAMAGED... CORRECTION:REMOVE THE DRIVELINE AND TRANS YOKE, INSTALL A NEW TRANS YOKE AND REPLACE BOTH U JOINTS AS REQUIRED...		0.00
TRG	001 BP	DAILY WORK SHEET TIME		588.00

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I authorize the repair work, parts, materials and hereby grant MDC permission to operate the vehicle herein described at MDC's discretion for the purpose of testing. A mechanic's lien will be against the above vehicle to secure the amount of repairs thereto. There will be 2% monthly interest charges for over 30 days. Attorney & court fees will be charged if necessary. I understand MDC is not responsible for delay or other consequences due to the unavailability of parts shipments beyond MDC's control. MDC is NOT responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond their control.

X _____

Labor : \$588.00

Parts : \$1,134.87

Sublet : \$0.00

Other Fees : \$35.00

Supplies : \$32.54

Subtotal : \$1,790.41

Sales Tax : \$70.04

Paid By : Total : \$1,860.45

On Account Paid : \$0.00

Pay Ref : Due : \$1,860.45

Mainland Diesel Corp.
PO Box 125 Burlington, KY 41005
11817 Old Lexington Pike
859-485-2471
859-586-6377 Fax

Repair Order # 0004213

Date : 4/29/2016

Page 1 of 1

Center : 1

Customer : BRASS EAGLE EXCAVATION

Address : 3248 RAINBOW TER.

City : ERLANGER, KY 41018-2229

Phone 1 : (859) 283-9028 Ext : MAIN

Phone 2 : (859) 512-5022 Ext : CELL

Vehicle : 1987 MACK R686ST

Unit : 03

HP : 300

VIN : 009139

Fleet #:

Engine : MACK

Trans : 9

Mileage : 117233

Parts

Quan	Part Number	Description	Price
1.00	FIT-700-20-BLK	HEAT SHRINK TUBING	4.71
1.00	FIT-700-20-RED	HEAT SHRINK TUBING	4.71
2.00	D6224-1114	BATT POS	51.84
2.00	BC12061	CABLE BATTERY NEG	51.28
1.00	8600312	ALTERNATOR 28SI J M	290.24
2.00	505N-BLK-SS	NUT BATTERY	2.70
2.00	505N-RED-SS	NUT BATTERY	2.70
4.00	505	NUT BATT	5.40
4.00	31S925	BATTERY 925 CCA	445.52
8.00	3/8 NUT	COURSE NUT	3.12
8.00	3/8 FLAT	FLAT WASHER	5.28
5.00	3/8 ALL TREAD	TREADED ROD	13.50
1.00	MUD FLAP	BATTERY TRY	11.48
4.00	J385-38	BATTERY LUG	32.40
1.00	24-7753	PULLEY ALTERNATOR V	37.80

Payments:

OnAcct, on 04/29/16 \$1750.93

Labor

Op	Tech	Description	Time	Charge
AL 002	DTB	COMPLAINT:CHECK OUT NO START		500.00
		CAUSE:6 VOLT BATTERY'S FAILED		
		CORRECTION:REMOVE OLD 6 VOLT BATTERY'S,		
		CHECK CHARGING SYSTEM TO CONVERT OVER		
		FROM 6 VOLT TO 12 VOLT BATTERY'S...		
		CUT OLD ENDS FROM BATTERY CABLES ON		
		TRUCK, CRIMP NEW ENDS ON CABLES AND HEAT		
		SHRINK ENDS...		
		CUT NEW BATTERY TIE DOWNS AND WELD ENDS,		
		CUT MUDD FLAPS TO COVER BATTERY'S,		
		INSTALL NEW BATTERY'S WITH TIE DOWNS...		
		START AND CHECK OPERATION...		
AL 001	MAM	COMPLAINT:CHECK CHARGING SYSTEM...		196.00
		CAUSE:FAILED ALTERNATOR...		
		CORRECTION:REPLACE AS REQUIRED...		

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

OK

I authorize the repair work, parts, materials and hereby grant MDC permission to operate the vehicle herein described at MDC's discretion for the purpose of testing. A mechanic's lien will be against the above vehicle to secure the amount of repairs thereto. There will be 2% monthly interest charges for over 30 days. Attorney & court fees will be charged if necessary. I understand MDC is not responsible for delay or other consequences due to the unavailability of parts shipments beyond MDC's control. MDC is NOT responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond their control.

X

Labor : \$696.00

Parts : \$962.68

Sublet : \$0.00

Other Fees : \$0.00

Supplies : \$32.54

Subtotal : \$1,691.22

Sales Tax : \$59.71

Paid By : Total : \$1,750.93

On Account

Pay Ref : Paid : \$0.00

Due : \$1,750.93